Page 1

From:

"Spencer, John" < John. Spencer@Simplot.Com> <caustren@utah.gov>, <lheppler@utah.gov>

To: Date:

6/7/2011 11:00 AM Formal Spill Report

Subject:

Attachments: Spill report 6-03-11 Cover Letter.pdf; Spill Report 6-02-11.pdf

The attached documents are the follow-up formal written Spill Report for the spill that occurred on June 2, 2011.

If you have any questions please give me a call.

John B. Spencer

Environmental / Senior Mining Engineer

Simplot Phosphates LLC

9401 N. Hwy 191

Vernal, UT 84078

Ph (435) 781-3348

Fax (435) 781-3332

Cell (435) 621-2629

John.Spencer@Simplot.com <mailto:John.Spencer@Simplot.com>

Bringing Earth's Resources to Life

Simplot Phosphates LLC Chemical Spill Report

Date of spill:	June 2, 2011
Time of spill:	5:15 pm
Location of spill:	Ore Stockpile
Estimated amount of spill (gallons):	120 gallons
Type of material spilled:	Hydraulic Oil
Date of Chemical Spill Report:	June 2, 2011 @ 6:25 pm
Existing Weather conditions:	Calm sunny & warm
Reported by:	John Spencer
Reported to (persons and/or agencies):	UDEQ & Corp
Other Persons Present:	Richard Deegan
Description and cause of spill: Unit 1266, the Cat 992 FEL, was removing material	
from around the pillars in the stockpile when a	hydraulic line broke. The FEL was moved
out of the stockpile area and immediately shu	t down. Maintenance replaced the broken
hydraulic line and refilled the FEL with 120 gall	lons of hydraulic oil.
Cleanup and control action taken: The FI	EL was repaired and utilized to load and
dump the contaminated ore and dirt into the	
through the mill. This oil contaminated ore an	
beneficiation. Diesel is a reagent used in the	
the process.	
Effectiveness of cleanup operations:	spill was on top of the ore where the spill
occurred and on dirt where it was parked out of	
contaminated with oil has all been processed	
remains	

In the Event of a Spill, Complete Form and Submit to the Environmental Department